NASA/TM-2003-212014



Nondestructive Evaluation of Ceramic Matrix Composite Combustor Components

Jiangang G. Sun Argonne National Laboratory, Argonne, Illinois

Michael J. Verrilli Glenn Research Center, Cleveland, Ohio

Robert R. Stephan Pratt & Whitney, East Hartford, Connecticut

Terry R. Barnett Southern Research Institute, Birmingham, Alabama

Greg C. Ojard United Technologies Research Center, East Hartford, Connecticut Since its founding, NASA has been dedicated to the advancement of aeronautics and space science. The NASA Scientific and Technical Information (STI) Program Office plays a key part in helping NASA maintain this important role.

The NASA STI Program Office is operated by Langley Research Center, the Lead Center for NASA's scientific and technical information. The NASA STI Program Office provides access to the NASA STI Database, the largest collection of aeronautical and space science STI in the world. The Program Office is also NASA's institutional mechanism for disseminating the results of its research and development activities. These results are published by NASA in the NASA STI Report Series, which includes the following report types:

- TECHNICAL PUBLICATION. Reports of completed research or a major significant phase of research that present the results of NASA programs and include extensive data or theoretical analysis. Includes compilations of significant scientific and technical data and information deemed to be of continuing reference value. NASA's counterpart of peerreviewed formal professional papers but has less stringent limitations on manuscript length and extent of graphic presentations.
- TECHNICAL MEMORANDUM. Scientific and technical findings that are preliminary or of specialized interest, e.g., quick release reports, working papers, and bibliographies that contain minimal annotation. Does not contain extensive analysis.
- CONTRACTOR REPORT. Scientific and technical findings by NASA-sponsored contractors and grantees.

- CONFERENCE PUBLICATION. Collected papers from scientific and technical conferences, symposia, seminars, or other meetings sponsored or cosponsored by NASA.
- SPECIAL PUBLICATION. Scientific, technical, or historical information from NASA programs, projects, and missions, often concerned with subjects having substantial public interest.
- TECHNICAL TRANSLATION. Englishlanguage translations of foreign scientific and technical material pertinent to NASA's mission.

Specialized services that complement the STI Program Office's diverse offerings include creating custom thesauri, building customized databases, organizing and publishing research results . . . even providing videos.

For more information about the NASA STI Program Office, see the following:

- Access the NASA STI Program Home Page at http://www.sti.nasa.gov
- E-mail your question via the Internet to help@sti.nasa.gov
- Fax your question to the NASA Access Help Desk at 301–621–0134
- Telephone the NASA Access Help Desk at 301–621–0390
- Write to:

NASA Access Help Desk NASA Center for AeroSpace Information 7121 Standard Drive Hanover, MD 21076

NASA/TM—2003-212014



Nondestructive Evaluation of Ceramic Matrix Composite Combustor Components

Jiangang G. Sun Argonne National Laboratory, Argonne, Illinois

Michael J. Verrilli Glenn Research Center, Cleveland, Ohio

Robert R. Stephan Pratt & Whitney, East Hartford, Connecticut

Terry R. Barnett Southern Research Institute, Birmingham, Alabama

Greg C. Ojard United Technologies Research Center, East Hartford, Connecticut

Prepared for the 29th Annual Review of Progress in Quantitative Nondestructive Evaluation (QNDE) sponsored by the Quantitative Nondestructive Evaluation Programs Bellingham, Washington, July 14–19, 2002

National Aeronautics and Space Administration

Glenn Research Center

Acknowledgments

This work was supported by the NASA Ultra-Efficient Technology Program and NASA contract NAS3–26385.
Trade names or manufacturers' names are used in this report for
identification only. This usage does not constitute an official
endorsement, either expressed or implied, by the National Aeronautics and Space Administration.
, and the state of

Available from

National Technical Information Service

5285 Port Royal Road Springfield, VA 22100

NASA Center for Aerospace Information

7121 Standard Drive

Hanover, MD 21076

Nondestructive Evaluation of Ceramic Matrix Composite Combustor Components

Jiangang G. Sun Argonne National Laboratory Argonne, Illinois 60439

Michael J. Verrilli National Aeronautics and Space Administration Glenn Research Center Cleveland, Ohio 44135

Robert R. Stephan
Pratt & Whitney
East Hartford, Connecticut 06108

Terry R. Barnett Southern Research Institute Birmingham, Alabama 35211

Greg C. Ojard United Technologies Research Center East Hartford, Connecticut 06108

Summary

Combustor liners fabricated from a SiC/SiC composite (silicon carbide fibers in a silicon carbide matrix) were nondestructively interrogated before and after combustion rig testing by x-ray, ultrasonic, and thermographic techniques. In addition, mechanical test results were obtained from witness coupons, representing the as-manufactured liners, and from coupons machined from the components after combustion exposure. Thermography indications correlated with reduced material properties obtained after rig testing. The thermography indications in the SiC/SiC liners were delaminations and damaged fiber tows, as determined through microstructural examinations.

Introduction

The pursuit of lower emissions and higher performance from gas turbine engines requires the development of innovative concepts, such as the use of advanced materials for key engine components. One such engine component is the combustor, where liners fabricated from a ceramic matrix composite, silicon carbide fibers in a silicon carbide matrix (SiC/SiC), are under evaluation. SiC/SiC composite technology has progressed from the fabrication of simple coupons to subelements and presently to actual components (refs. 1 to 4). This last area posed a significant challenge to nondestructive evaluation (NDE) techniques because of the complex geometries involved.

To evaluate SiC/SiC components in a combustion environment, the rich-burn, quick-quench, lean-burn (RQL) sector rig was designed and fabricated. The purpose of the sector rig testing was to demonstrate the structural durability of the SiC/SiC liners in a combustion environment where stresses,

temperatures, and pressures would as accurately as possible reflect the operating conditions found in a turbine engine.

X-ray, ultrasonic, and thermographic techniques were used to inspect the as-manufactured SiC/SiC components and the liners after combustion testing. The purpose of this study was to characterize the postexposure condition of one SiC/SiC combustor liner part through NDE evaluation via thermography and mechanical property measurement.

Experimental

Material and Component

Combustor liners were manufactured by Honeywell Advanced Composites from a SiC/SiC composite developed under the NASA Enabling Propulsion Materials program. A chemical-vapor-infiltrated, slurry-cast, and melt-infiltrated SiC matrix was reinforced with Sylramic SiC fibers. The fiber tows were woven into 5-harness satin weave cloth. More details on the SiC/SiC material can be found in reference 5.

The sector rig liner set consisted of 6 component geometries and a total of 28 liners (fig. 1). For this study, one of the six components, the lean-zone inside-diameter liner (LZID) was examined. The LZIDs are curved plates, each covering about a 30° arc of the total 60° sector, as shown in figure 1. A twelve-ply-thick leading edge reinforces the attachment hole region. The rest of the LZID is six plies thick. LZIDs containing 34- and 40-percent fiber volume were tested.

Flexure coupons were machined from the as-manufactured and exposed sector parts to obtain mechanical properties. The as-manufactured parts were supplied with extra material that was machined into test coupons. The exposed parts were machined to obtain test coupons of the same geometry as that used for the witness testing. Three-point flexure testing was conducted at 815 °C. Reference 6 gives more details on the mechanical test procedures.

Combustion Testing

The Preheated Combustor and Materials Test Facility (PCMTF) at NASA Glenn Research Center was used to conduct the RQL sector rig testing. Air temperature (T3), pressure (P3), and flow rate (W3) were varied to approximate the anticipated service cycle of the High Speed Civil Transport (HSCT) engine combustor (ref. 7). All aspects of an HSCT flight operation, such as takeoff, climb, cruise, and decent, are included in the 230-min test cycle.

The combustion testing was periodically interrupted to remove some of the SiC/SiC liners for postexposure analysis. After 260 hr of operation, the rig was disassembled and all SiC/SiC combustor liners were removed

NDE Techniques

As-manufactured and combustion-exposed SiC/SiC components were inspected using x-ray film radiographic, ultrasonic, and thermographic techniques. Radiography is sensitive to volumetric features, such as large voids and gross porosity or thickness variations, but cannot detect planar (laminar) features, such as delaminations in ceramic matrix composites. Ultrasonic techniques have a high sensitivity for the detection of delaminations, but a quantitative interpretation of the data is difficult as they are affected by many experimental setup parameters. Thermography techniques are also very sensitive to delaminations and when used in a through-transmission setup to determine thermal diffusivity, which is a material

property, the data can be quantitatively analyzed to relate with the detailed structures of defects (ref. 8). In this study, only the thermography results will be discussed.

A transient through-transmission (through-thickness) thermography method was used on the tested liners. Two high-energy flash lamps generate a heat pulse that travels through the thickness of the parts (fig. 2). The raw data consist of multiple-layered images acquired at 120 Hz. A total of 40 frames was typically suitable to capture the temperature rise. The analysis technique was based on that given by Parker (ref. 9). The front surface temperature rise is given by

$$T(L,t) = \frac{Q}{\rho CL} \left[1 + 2\sum_{n=1}^{\infty} (-1)^n \exp\left(-\frac{n^2 \pi^2}{L^2} \alpha t\right) \right]$$
 (1)

where T is the temperature, L is the liner thickness, t is the time elapsed, Q is the amount of heat absorbed by the liner from the flash lamps, α is the thermal diffusivity, ρ is the material density, and C is the specific heat of the material. Using the time to reach half the maximum detected temperature $(t_{1/2})$, the thermal diffusivity at each pixel can be calculated by

$$\alpha = \frac{1.37L^2}{\pi^2 t_{1/2}} \tag{2}$$

At regions of planar defects, such as delaminations, the material surface temperature is lower than that of the undamaged composite and will take a longer $t_{1/2}$ to reach the equilibrium part temperature (note that the part will eventually reach an equilibrium constant temperature if sufficient time is given). Therefore, from equation (2), the regions with damaged material will have lower thermal diffusivities.

The thermal diffusivity calculated from equation (2) is proportional to the thickness squared. Because it is impossible to provide thickness values for all pixels of an imaged part, it is common to use a representative thickness (typically the averaged thickness) for the calculation of the diffusivity image for the entire part. This method has some shortcomings when thickness variation is large. For example, in the case of a uniform material of constant diffusivity, equation (2) dictates that for a pixel with a thickness twice that of a second pixel, the half-rise time $t_{1/2}$ at the first pixel will be four times longer than that of the second. However, if we choose to use the thickness of the second pixel for calculating diffusivities at all pixels, the calculated diffusivity at the first pixel would appear to be four times lower than its real diffusivity. Similarly, the diffusivity calculated from equation (2) appears to be higher for a thinner pixel. Therefore, care should be taken when interpreting measured diffusivity images. Note that this equation is exact when a test part has a uniform thickness.

Results

An example of thermography results obtained for three LZIDs after 115 hr of sector rig testing is shown in figure 3. Part 216–1 contains 34-percent fiber volume fraction, and the other two contain 40 percent. The thickness of the middle sections of the liners was used to calculate the diffusivity values in the image. The apparent diffusivities are lower at the strips with fastener holes where the material is thicker and are higher at the left edges where the material is thinner. In addition to these diffusivity variations due to a thickness change, regions with considerably lower diffusivities can be observed in all liners, especially for 216–1.

To investigate the origin of local lower diffusivity values, a LZID was sectioned and polished. Figure 4 shows the microstructure of a cross section taken from 216–1. The line on the thermography image in figure 3 shows the location of the cross section. Damaged SiC fiber tows and delamination

cracks can be seen. The diffusivity reduction shown in figure 3 is related to the damage (i.e., delamination) of the ceramic matrix composite material due to the sector testing. For a single delamination, Sun (ref. 8) showed that the diffusivity reduction could be used to determine the (air gap) thickness of the delamination.

Thermal diffusivity data for another LZID with 34-percent fiber volume, which was exposed in the combustion environment for 145 hr, is shown in figure 5. Thermal diffusivity values are plotted in figure 5(a) along seven horizontal lines passing through several interesting regions in the thermal diffusivity image of 216–2. Although there is a thickness variation near both vertical edges of the liner, the thickness is uniform in the middle section and this value is used in the diffusivity calculation. In this middle section, the measured diffusivity is uniform in undamaged regions (e.g., line 7). Reduced diffusivity representing damage of varying severity is shown in other regions (lines 1 to 6). Figure 5(b) plots the width-averaged diffusivity along the length for the regions where four coupons were machined from the part to obtain flexure strength. It is apparent that coupons 2 to 4 contained large damaged areas with significant thermal diffusivity reductions and that coupon 1 had only slight damage near the region of thickness transition at the right. It is interesting to note that fracture occurred near the locations where the lowest diffusivities were observed for coupons 2 to 4.

Flexure strengths obtained from these coupons are compared with the thermal diffusivity in table I. The postexposure strength obtained from these coupons decreased with the decreasing ratio of the coupon-averaged thermal diffusivity to the mean thermal diffusivity (α/α_m), revealing the correlation between the thermal diffusivity data and strength.

The normalized flexure strength versus combustion exposure time for coupons machined from all LZIDs tested in the sector rig is shown in figure 6. The normalized flexure strength was calculated as the ratio of the strength of a coupon machined from a tested LZID to the average as-fabricated strength obtained from the LZID witness coupons for the same part. The strength decreases with increasing exposure time for the parts with 34-percent fiber volume, whereas the strength of the 40-percent fiber volume decreased after 115 hr of exposure. Also, coupons machined from component regions with thermography indications had lower strengths than coupons from regions with no NDE indications. As a function of exposure time, the strength data sets for coupons with and without NDE indications follow the same trends.

Summary

- 1. Combustor liners fabricated from SiC/SiC were tested in an aircraft engine environment using the rich-burn, quick-quench, lean-burn (RQL) sector rig for up to 260 hr. SiC/SiC liners were periodically removed during the rig operation to conduct postexposure analyses.
- 2. Degradation of the SiC/SiC material occurred and was in the form of delaminations and damaged fiber tows for the combustor liner parts examined, namely, the lean-zone inside-diameter liners (LZIDs).
- 3. Thermography was effective in imaging this damage in the SiC/SiC liners, whereas radiography and ultrasonic inspections were less sensitive.
- 4. Strength was measured by testing coupons machined from combustion-exposed parts and compared with witness (as-manufactured) data. For parts with 40-percent fiber volume, the strength decreased after 115 hr. However, exposure of only 10 hr decreased the strength of parts with 34-percent fiber volume.
- 5. For the exposed parts, coupons machined from regions that had thermography indications had lower strengths than coupons machined from regions that had no indications.
- 6. Local thermal diffusivity correlated with measured coupon strength for exposed SiC/SiC combustor liners.

References

- 1. Brewer, D.; Ojard, G.; and Gibler, M.: Ceramic Matrix Composite Combustor Liner Rig Test. ASME Paper TE00CER03–03, 2000.
- 2. Miriyala, Narendernath; Fahme, Anthony; and van Roode, Mark: Ceramic Stationary Gas Turbine Program—Combustor Liner Development Summary. ASME 2001–GT–0512, 2001.
- 3. Corman, Gregory, et al.: Rig and Gas Turbine Engine Testing of MI–CMC Combustor and Shroud Components. ASME 2001–GT–0593, 2001.
- 4. Igashira, Ken-Ichiroh, et al.: Development of the Advanced Combustor Liner Composed of CMC/GMC Hybrid Composite Material. ASME 2001–GT–0511, 2001.
- 5. Brewer, David: HSR/EPM Combustor Materials Development Program. Mater. Sci. Eng., vol. A261, 1999, pp. 284–291.
- Verrilli, Michael J., et al.: Evaluation of Post-Exposure Properties of SiC/SiC Combustor Liners Tested in the RQL Sector Rig. NASA TM—2002-211380, 2002. http://gltrs.grc.nasa.gov/cgi-bin/GLTRS/browse.pl?2002/TM-2002-211380.html Accessed Jan. 6, 2003.
- 7. Shaw, Robert J.; Koops, Leigh; and Hines, Richard: Progress Toward Meeting the Propulsion Technology Challenges for a 21st Century High-Speed Civil Transport. NASA TM-113161 (ISABE-97-7045), 1997. http://gltrs.grc.nasa.gov/cgi-bin/GLTRS/browse.pl?1997/TM-113161.html Accessed Jan. 7, 2003.
- 8. Sun, J.G.: Analysis of Quantitative Measurement of Defect by Pulsed Thermal Imaging. Paper presented at the Review of Progress in Quantitative NDE, Brunswick, ME, 2001.
- 9. Parker, W.J., et al.: Flash Method of Determining Thermal Diffusivity, Heat Capacity, and Thermal Conductivity. J. Appl. Phys., vol. 32, no. 9, 1961, pp. 1679–1684.

TABLE I.—COMPARISON OF THERMAL DIFFUSIVITY AND COUPON STRENGTH FOR LEAN-ZONE INSIDE-DIAMETER LINER (LZID) 216–2 AFTER 145 HR OF TESTING IN COMBUSTION ENVIRONMENT

Coupon	Ratio of coupon-averaged thermal	Posttest 815 °C
	diffusivity to mean thermal diffusivity,	flexure strength,
	$\alpha/\alpha_{\mathrm{m}}$	MPa
1	1.0	262
2	.6	229
3	.56	207
4	.47	131




Figure 1.—Rich-burn, quick-quench, lean-burn (RQL) sector rig and images of all SiC/SiC parts.




Figure 2.—Through-transmission (through-thickness) thermography test configuration.




Figure 3.—Thermography of three SiC/SiC liners after 115 hr of sector rig testing. Part 216–1 contains 34-percent fiber volume fraction; parts 208–2 and 218–2 contain 40-percent fiber volume fraction.




Figure 4.—Microstructure of LZID 216–1 after 115 hr of combustion exposure (black line in fig. 3 shows location of this section). Note the arrows that indicate damaged tows.




Figure 5.—Thermal diffusivity data for LZID 216–2 after 145 hr of combustion exposure. (a) Line plots at seven part locations. Note: line 7 is reference level. (b) Average values for regions of coupons machined for strength measurement.




Figure 6.—Normalized flexure strength data obtained at 815 °C as function of exposure time for coupons machined from LZIDs. (a) Data for coupons from 34-percent fiber volume parts. (b) Data for coupons from 40-percent fiber volume parts.

REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

I. AGENCY USE ONLY (Leave blank)	Z. REPORT DATE	3. REPORT TIPE AND	D DATES COVERED			
	April 2003	Te	echnical Memorandum			
4. TITLE AND SUBTITLE	1		5. FUNDING NUMBERS			
Nondestructive Evaluation of Ce	ramic Matrix Composite C					
			WBS-22-714-04-15			
6. AUTHOR(S)			,, <u>ps 22 , 11 or 10</u>			
Jiangang G. Sun, Michael J. Verr Greg C. Ojard	illi, Robert R. Stephan, Ter	rry R. Barnett, and				
7. PERFORMING ORGANIZATION NAME(S	S) AND ADDRESS(ES)		8. PERFORMING ORGANIZATION			
National Aeronautics and Space	A dministration		REPORT NUMBER			
John H. Glenn Research Center a Cleveland, Ohio 44135–3191	E-13702					
9. SPONSORING/MONITORING AGENCY N	IAME(S) AND ADDRESS(ES)		10. SPONSORING/MONITORING AGENCY REPORT NUMBER			
N			AGENCT REPORT NUMBER			
National Aeronautics and Space	Administration					
Washington, DC 20546-0001			NASA TM-2003-212014			
-						
11. SUPPLEMENTARY NOTES						
	, Bellingham, Washington, Ju	ly 14–19, 2002. Jiangang ((QNDE) sponsored by the Quantitative G. Sun, Argonne National Laboratory, an, Pratt & Whitney, East Hartford,			
			211; Greg C. Ojard, United Technologies organization code 5160, 216–433–3337.			
		person, whender y. verrini,				
12a. DISTRIBUTION/AVAILABILITY STATE	MENI		12b. DISTRIBUTION CODE			
Unclassified - Unlimited						
Subject Categories: 24 and 35	Distrib	ution: Nonstandard				
	Available electronically at http://gltrs.grc.nasa.gov					
This publication is available from the l	NASA Center for AeroSpace Int	formation, 301–621–0390.				
13. ABSTRACT (Maximum 200 words)						
Combustor liners fabricated from nondestructively interrogated bet niques. In addition, mechanical t liners, and from coupons machin correlated with reduced material liners were delaminations and da	Fore and after combustion rest results were obtained freed from the components af properties obtained after ri	ig testing by x-ray, ultra from witness coupons, re- fter combustion exposure g testing. The thermogra	sonic, and thermographic tech- presenting the as-manufactured e. Thermography indications apply indications in the SiC/SiC			
14. SUBJECT TERMS Nondestructive tests; Ceramic m	-	ion; Silicon carbide;	15. NUMBER OF PAGES 15. 16. PRICE CODE			
Composite structures; Mechanica	al properties		1.5			
	ECURITY CLASSIFICATION OF THIS PAGE	19. SECURITY CLASSIFICA OF ABSTRACT	TION 20. LIMITATION OF ABSTRACT			

Unclassified

Unclassified

Unclassified